



"Wood, Thomas"
<TRWOOD@stoel.com>
05/19/2006 04:23 PM

To Margaret Alkon/R9/USEPA/US@EPA
cc gyee@arb.ca.gov, kathi.hann@BHPBilliton.com,
Rick.Abel@BHPBilliton.com, oceanair1@worldnet.att.net,
tumenhofer@entrinx.com, Laura
bcc

Subject Sause Brothers Report

History:



This message has been forwarded.

Margaret: We had a good conversation with Gary Yee and his staff this afternoon regarding the Sause Brothers repower report. Gary noted that there was an inconsistency in the engine model reference on page 2 and 3 as compared to the rest of the document and attachments. Specifically, the existing engine type was listed as a "EMD 12-645E6" engine while everywhere else it was listed as a "EMD 16-645E6" engine. The existing engines are indeed 16 cylinder engines, as is noted in the vessel spec sheet included as last page of Attachment E. Therefore, the correct model is "EMD 16-645E6." The attached report, with revision date 5/19/06, reflects the correct model throughout and should replace the version of the report that I provided to you yesterday. The attachments have not changed, but to avoid any confusion I am enclosing a copy of those as well.

Sorry to keep replacing the document, but I want to ensure that the public version contains no errors. Let me know if you have any questions.

Tom

Thomas R. Wood
Stoel Rives LLP
Phone: (503) 294-9396
Fax: (503) 220-2480
Cell: (503) 349-4845



Klihyam Repower Report-5-19-06 edits.pdf



attachments-5-19-06.pdf